ADDENDUM

Masters created with the MASTER CREATION subsystem will not boot. A protected master must be duplicated with the DISKETTE DUPLICATION subsystem in order to produce working copies.

Some error messages may appear during booting of Lock-It-Up diskettes:

ERR1 - write protect required but not present

ERR2 - Autostart ROM required but not present

ERR3 - Invalid copy